Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1893

Created: 11/21/2025
Invoiced: 12/05/2025
Payment Term: On Receipt
Payment Due: 12/05/2025
Service Writer: Robert Powers

[redacted]

1999 Land Rover Defender 90
VIN: SALLDVBB8XA173892

Customer Comments
Bulkhead Removal Front Skid Plate MPH Gauges Wood Steering Wheel (Silver Spoke) License Plate Bracket Extra Key Cut

Bulkhead Removal

	Description	Price	QTY	HRS	Subtotal
1	Install Bulkhead Removal Kit			8	$1,320.00
2	Bulkhead Removal Kit	$455.55	1		$455.55
3	Refit and Reinstall carpet for the bulkhead removal	$550.00			$550.00
		Shop Supplies: $25.00	Tax (8%): $38.44		Total: $2,388.99

Exterior

	Description	Price	QTY	HRS	Subtotal
1	Install Skid Plate			2	$330.00
2	Install License Plate Bracket			0.4	$66.00
3	Install 2"Hitch Receiver			1.5	$247.50
4	Remove Steps			1	$165.00
5	Front Skid Plate	$499.00	1		$499.00
6	License Plate Bracket Holder Euro to US Tag	$20.00	1		$20.00
7	2" Hitch Receiver Land Rover *Part #: 23423*	$179.48	1		$179.48
8	Shipping	$78.73	1		$78.73
9	Headlight, Pair, LED	$225.00	1		$225.00
		Shop Supplies: $25.00	Tax (8%): $82.18		Total: $1,917.89

Interior

Speedometer over lay goes on the outside of the instrument cluster.
Spare key will be cut by third party.

	Description	Price	QTY	HRS	Subtotal
1	Install Steering Wheel			1	$165.00
2	Install Shift Knobs			0.2	$33.00
3	Steering Wheel, Wood	$372.00	1		$372.00

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1893

Created: 11/21/2025
Invoiced: 12/05/2025
Payment Term: On Receipt
Payment Due: 12/05/2025
Service Writer: Robert Powers

Interior			
4 Steering Wheel Boss	$71.02	1	$71.02
5 Shift Knobs	$125.91	1	$125.91
6 Courtesy Lamp Switch *Part #: PLL127*	$19.56	1	$19.56
7 Spare Key	$6.67		$6.67
	Shop Supplies: $25.00	Tax (8%): $49.08	**Total: $867.24**

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

This shop charges a 3% credit card processing fee.

Labor	$2,326.50
Parts	$2,046.25
Subcontracts	$556.67
Subtotal	$4,929.42
Shop Supplies	$75.00
EPA	$0.00
Tax	$169.70
Grand Total	$5,174.12
Paid to Date	($5,174.12)
REMAINING BALANCE	**$0.00**

Payments		
1/10/2026	Check #194	$5,174.12
Total Payments		$5,174.12

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1882

Created: 11/17/2025
Invoiced: 12/04/2025
Payment Term: On Receipt
Payment Due: 12/04/2025
Service Writer: Robert Powers

[redacted]

1999 Land Rover Defender 90
VIN: SALLDVB88XA173892
Mileage: 253,578 km

Mechanical

Includes upgraded turbo and downpipe. In the future we can add an intercooler, intake pipe, and ECU tune to increase power with uprated turbo.

	Description	Price	QTY	HRS	Disc	Subtotal
1	R&R Glow Plugs			1.25		$206.25
2	R&R Injector Harness and Valve Cover Gasket			3		$495.00
3	R&R Turbo			5		$825.00
4	Check Tune of ECU			1		$165.00
5	Down Pipe w/ Flex Pipe			1.5		$247.50
6	Flush Front Differential			1		$165.00
7	4 bar map sensor			0.5		$82.50
8	Oil & Filter R&R			0.5		$82.50
9	R&R glow plug harness			1		$165.00
10	Glow Plug	$37.85	4			$151.40
11	TD5 Fuel Injector Harness	$89.99	1			$89.99
12	Valve Cover Sealing Grommet Td5	$7.88	13			$102.44
13	Valve Cover Gasket Land Rover TD5 1998-2001	$41.64	1			$41.64
14	Hybrid Turbo Package, 4 Bar Sensor, Filter (Uprated)	$2,054.57	1		100%	$0.00
15	TD5 Turbocharger Gasket Kit with Studs	$101.40	1			$101.40
16	Stainless Td5 2.5" 10P Downpipe	$217.33	1			$217.33
17	75w90 Gear	$9.98	2			$19.96
18	Glow Plug Harness Land Rover Td5	$259.58	1			$259.58
19	Empire Defender Custom Intercooler	$533.33	1			$533.33
20	TD5 ITG	$53.33	1			$53.33
21	Shipping	$162.00	1			$162.00
22	Td5 Oil Filter	$21.53	1			$21.53
23	Rotary Oil Filter	TD5	$34.53	1		$34.53
24	Drain Plug - Engine Oil - TD5	$3.60	1			$3.60
25	Washer - Sump Plug - Td5	$0.68	1			$0.68
26	Oil 10W30	$7.21	8			$57.68

Discount (32.41%): $2,054.57 Shop Supplies: $25.00 Tax (8%): $150.03 **Total: $4,459.20**

Steering

Description	Price	QTY	HRS	Subtotal

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1882

Created: 11/17/2025
Invoiced: 12/04/2025
Payment Term: On Receipt
Payment Due: 12/04/2025
Service Writer: Robert Powers

Steering				
1 HD Steering Arms R&R			3	$495.00
2 Drop Arm R&R			1.2	$198.00
3 3rd Ball Joint (Fulcrum Joint) R&R			1.4	$231.00
4 Heavy Duty Steering Rod Set Land Rover Defender *Part #: TF250*	$388.35	1		$388.35
5 Drop Arm With Ball Joint For LHD Power Steering Box *Call to Order*	$183.94	1		$183.94
6 Fulcrum Point Rear A Arm Ball Joint Assy	$149.00	1		$149.00
7 Fulcrum A Arm Ball Joint Hardware Kit	$21.50	1		$21.50
		Tax (8%): $59.42		Total: $1,726.21

Electrical		
Description	HRS	Subtotal
1 Install LED Light Kit	3	$495.00
2 Diagnose Rear Wiper *Needs motor and switch*	1	$165.00
3 Standard Size 9 Part LED Light Kit Smoked for Series & Defender 1958-2016 *Part #: V-20431002*		$212.31
Tax (8%): $16.98		Total: $889.29

Interior		
Description	HRS	Subtotal
1 Diagnose Lock, Driver *Needs door parts*	0.5	$82.50
2 Diagnose Interior Light not Turning on *Needs door switches*	0.5	$82.50
3 Check Heater to Make Sure Working Properly	1	$165.00
Shop Supplies: $25.00 Tax (8%): $2.00		Total: $357.00

Exterior				
Would like hinge on driver side to match the passenger side. Only wants the driver side hinge replaced.				
Description	Price	QTY	HRS	Subtotal
1 Door Hinges, Front Driver			2.5	$412.50
2 Vent Flap Seal R&R			1	$165.00
3 Alloy Front Door Hinge Kit Land Rover Defender 90	$228.03	1		$228.03
4 O-Ring Hinge to door *Nylon Washer - Bolt - Hinge To Door* *PLE255*	$1.83	8		$14.64

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1882

Created: 11/17/2025
Invoiced: 12/04/2025
Payment Term: On Receipt
Payment Due: 12/04/2025
Service Writer: Robert Powers

Exterior			
5 Seal Dash Vent-Bulkhead Defender Foam Type	$28.69	2	$57.38
6 Bulkhead Vent Flap Pin Kit - Stainless Steel *Defender*	$34.95	1	$34.95
7 Front Grill Surround for TD5 AC	$263.64	1	$263.64
8 Paint Hinges	$200.00		$200.00
9 Paint Grill Frame			$0.00
Shop Supplies: $25.00	Tax (8%): $49.89		Total: $1,451.03

Brakes

Includes bleeding brakes at 4 corners and fluid flush.

Description	Price	QTY	HRS	Subtotal
1 Master Cylinder R&R			1.8	$297.00
2 Brake Booster R&R			2.2	$363.00
3 Brake Pads, Rear R&R			0.9	$148.50
4 Brake Rotor, Rear Both R&R			1.4	$231.00
5 Breke Caliper Front R&R Both Sides			1.5	$247.50
6 Master Cylinder	$249.95	1		$249.95
7 Brake Booster	$411.89	1		$411.89
8 Brake Rotor, Rear	$164.39	2		$328.78
9 Brake Pads, Rear	$52.53	1		$52.53
10 Brake Caliper Assembly Front Right	$194.59	1		$194.59
11 Brake Caliper Assembly Front Left	$194.59	1		$194.59
12 Brake Fluid DOT 5	$11.99	4		$47.96
13 Import & Shipping	$127.31	1		$127.31
Shop Supplies: $25.00	Tax (8%): $130.61			Total: $3,050.21

Suspension

Springs provide a 1" lower riding height and increase the ride comfort. These are a premium road spec custom suspension. The ride quality is also increased.

Tariff is estimated based off current duty rate for UK parts. This rate can change depending on country of manufacture or at the will of the import agent.

Description	Price	QTY	HRS	Subtotal
1 Shocks R&R			2.2	$363.00
2 Coil Springs R&R			3.1	$511.50
3 Road Spec Comfort Springs For Defender 90	$1,112.31	1		$1,112.31
4 Bilstein B6 Shocks w Steering Damper Kit	$789.23	1		$789.23

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1882

Created: 11/17/2025
Invoiced: 12/04/2025
Payment Term: On Receipt
Payment Due: 12/04/2025
Service Writer: Robert Powers

Suspension				
5	Shipping	$622.00	1	$622.00
6	Import Tariffs	$240.00	1	$240.00
7	Alignment	$120.00		$120.00
			Tax (8%): $221.08	Total: $3,979.12

Engine/Transmission/Transfer Box Seals			
Description		**HRS**	**Subtotal**
1	Hot Pressure Wash/Steam Clean Undercarriage and Engine Bay	1.25	$206.25
2	Diagnose Engine Leaks	0.5	$82.50
	Shop Supplies: $25.00	Tax (8%): $2.00	Total: $315.75

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

This shop charges a 3% credit card processing fee.

Labor	$7,375.50
Parts	$9,829.87
Subcontracts	$320.00
Subtotal	$17,525.37
Discount	$2,054.57
Shop Supplies	$125.00
EPA	$0.00
Tax	$632.02
Grand Total	**$16,227.82**
Paid to Date	($16,227.82)
REMAINING BALANCE	**$0.00**

Payments		
11/19/2025	Credit card ending in 1002	$8,000.00
	3% credit card processing fee.	$240.00
12/12/2025	Check #101	$8,227.82
Total Payments		$16,467.82

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1919

Created: 12/08/2025
Invoiced: 01/12/2026
Payment Term: On Receipt
Payment Due: 01/12/2026
Service Writer: Billy Fishpaw

[redacted]

1999 Land Rover Defender 90
VIN: SALLDVB88XA173892

Customer Comments

Once the head was removed, we noticed that both of the dowels are broken and will need replacing. The head gasket was starting to leak on cylinder 5. Also, during disassembly of the head we noticed that the spring on one of the injectors is broken. That will also need replacing.

Oil pump was replaced April 2022

Head Gasket

	Description	Price	QTY	HRS	Subtotal
1	Head Gasket R&R			20	$3,300.00
2	AC Evac and Recharge			1	$165.00
3	Coolant Flush			1	$165.00
4	Injector Programming and Sync to ECU			1.25	$206.25
5	Harmonic Balancer R&R			1	$165.00
6	Head Gasket, 1 Hole	$60.21	1		$60.21
7	Head Bolts	$95.05	1		$95.05
8	Camshaft Timing Pins	$28.49	1		$28.49
9	Timing Chain and Tensioner	$502.33	1		$502.33
10	Head Hardware Kit	$97.03	1		$97.03
11	Head Locating Dowel	$3.16	2		$6.32
12	TD5 Gasket Set	$123.65	1		$123.65
13	Oil Pan Gasket	$67.18	1		$67.18
14	Water Pump	$108.39	1		$108.39
15	Water Pump Gasket	$9.45	1		$9.45
16	Thermostat	$40.61	1		$40.61
17	Injector Seals	$1.40	10		$14.00
18	Crankshaft Seal	$28.55	1		$28.55
19	10w30 Rotella	$7.19	8		$57.52
20	Injector - Blue Td5 Up to 2002 - 10P Engine	$789.38	1		$789.38
21	Fuel Pressure Regulator, TD5 *Part # LR016318*	$172.80	1		$172.80
22	Parts Shipping	$104.55	1		$104.55
23	Parts Shipping	$114.78	1		$114.78
24	O-ring, Filter Housing	$4.72	1		$4.72
25	Serpentine Belt Tensioner	$204.09	1		$204.09

Car Cave USA
1120 Edgefield Highway
Aiken, SC 29801
(803) 262-4742
www.carcaveusa.com

Invoice #1919

Created: 12/08/2025
Invoiced: 01/12/2026
Payment Term: On Receipt
Payment Due: 01/12/2026
Service Writer: Billy Fishpaw

Head Gasket			
26 Max Euro Teal Coolant *Part #: AFI6110*	$20.24	2.5	$50.60
27 Harmonic Balancer *Part #: LHG100580*	$550.00	1	$550.00
28 Machine Work	$250.00		$250.00
29 Paint Grill Frame	$150.00		$150.00
	Shop Supplies: $25.00	Tax (8%): $260.38	Total: $7,916.33

Heater				
Description	Price	QTY	HRS	Subtotal
1 R&R Blower Motor			5	$825.00
2 Courtesy Lamp Switch R&R			1	$165.00
3 Motor & Fan Heater LHD Defender	$308.76	1		$308.76
	Shop Supplies: $25.00	Tax (8%): $26.70		Total: $1,350.46

7 Way Plug				
Description	Price	QTY	HRS	Subtotal
1 Install 7 Way Hitch Plug			1.5	$247.50
2 7 Way/4 Way Flat Harness	$30.39	1		$30.39
		Tax (8%): $2.43		Total: $280.32

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

This shop charges a 3% credit card processing fee.

Labor	$5,238.75
Parts	$3,568.85
Subcontracts	$400.00
Subtotal	$9,207.60
Shop Supplies	$50.00
EPA	$0.00
Tax	$289.51
Grand Total	**$9,547.11**
Paid to Date	($0.00)
REMAINING BALANCE	**$9,547.11**