CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
GET OUR MOBILE APP ON APPLE OR ANDROID!

Repair Order #0068719 3/30/2020 5:15 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage :
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGAND
Othe : 993 C4S
Unit # 4 WHEEL DRIVE

Your Service Writer Today Is: KATE COURTNEY Center: RETAIL

Service Requests:
ALIGNMENT RACK- went into the ditch.

Category Summary	Parts	Labor	Job Total
EXHAUST SYSTEM	$4,432.00	$372.50	$4,804.50

Technician	Service Description			Parts	Labor	Job Total
05	**REMOVE AND REPLACE MUFFLER AND REPAIR DAMAGE TO AREA.**			**4432.00**	**372.50**	**4804.50**
S	*COVER*	*712.25*	*1*	*712.25*		
S	*PIN*	*8.67*	*5*	*43.35*		
S	*SPRING*	*2.73*	*5*	*13.65*		
S	*WASHER*	*8.67*	*5*	*43.35*		
S	*REAR MUFFLER*	*860.49*	*1*	*860.49*		
S	*MUFFLER BRACKET*	*143.45*	*1*	*143.45*		
S	*HXHD*	*4.94*	*2*	*9.88*		
S	*HEATER*	*240.56*	*1*	*240.56*		
S	*HEATER*	*240.56*	*1*	*240.56*		
S	*HEAT CONTROL BOX*	*1025.67*	*2*	*2051.34*		
S	*HOSE CLAMP*	*9.14*	*8*	*73.12*		

2051.34

$2,753.16 — Will's Parts
+ 500

Repair Order Notes
NVD - 3/26 - LMVM ON CLAIMS ADJUSTOR'S PHONE LETTING HIM KNOW WE HAVE THE QUOTE READY TO GO.

*****TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.**
*****OUR WARRENTY:12 Months or 12000 Miles on parts and labor, which ever comes first**

PLEASE BE ADVISED: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

****TERMS:COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.**

We will charge $35.00 a day for all vehicles left in our lot after 48 hours.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$4,432.00
TOTAL LABOR	$372.50
SUBLET	$0.00
Supply Charg	$35.00
SUBTOTAL	$4,839.50
OTHER FEES	$0.00
SALES TAX	$336.14
REPAIR ORDER TOTAL	**$5,175.64**
PAID	$0.00
DUE	$5,175.64

LaMettry's®
Collision, Glass and More!

LaMettry's Collision, Glass, and More Chanhassen

"Every Customer Leaves with a Smile"
1650 Motorplex Court, Chanhassen, MN 55317
Phone: (952) 405-7300

Workfile ID: 74d1f6e3
PartsShare: 5PnFMn

Final Bill

RO Number: 904730

Customer:

Millrace MOTOR CLUB

Insurance: SELF PAY

Adjuster:
Phone:
Claim:
Loss Date:
Deductible: PPF

Estimator: Jesse O'Bryan
Create Date: 4/15/2020

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

VIN: WP0AA2992TS321853
License: 664LVE
State: MN

Interior Color:
Exterior Color: Maroon
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out: 6/11/2020
Job #:

Line	Ver	Operation	Description	Qty	Extended Price $	Part Type	Labor	Type	Paint
1	E01		Additonal Primer				2.0	Body	
2	E01		**HOOD**						
3	E01	Repair	Hood				3.0	Body	
4	E01		**FENDER**						
5	E01	Repair	RT Fender w/o turbo, 4S				3.0	Body	
6	E01	Repair	LT Fender w/o turbo, 4S				3.0	Body	
7	E01	Repair	Windshield Frame				6.0	Body	2.5
8	E01		**DOOR**						
9	E01	Remove/Replace	LT Weatherstrip around door coupe	1	671.70T	OEM	1.0	Body	
10	E01	Remove/Replace	Clear Guard Hood, Fenders, Bumper, Headlights, Door Cup	1	1,560.00T	Other			

Estimate Totals	Discount $	Markup $	Rate $	Total Hours	Total $
Parts					2,231.70
Labor, Body			58.00	18.0	1,044.00
Labor, Refinish			58.00	2.5	145.00
Material, Paint					95.00
Subtotal					**3,515.70**
Bottomline Discount					(351.57)
Sales Tax					154.43
Grand Total					**3,318.56**
Net Total					**3,318.56**

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

LaMettry's®
Collision, Glass and More!

LaMettry's Collision, Glass, and More Chanhassen

"Every Customer Leaves with a Smile"
1650 Motorplex Court, Chanhassen, MN 55317
Phone: (952) 405-7300

Workfile ID: b2ba65bd
PartsShare: 5NhRgF

Final Bill

RO Number: 904647

Customer: [redacted]

Millrace MOTOR CLUB

[redacted]

Adjuster: MARCUS DAVIS
Phone: (919) 278-9144 Business
[redacted]

Estimator: Jesse O'Bryan
Create Date: 3/19/2020

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

VIN: WP0AA2992TS321853
License: 664LVE
State: MN

Interior Color:
Exterior Color: Maroon
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out: 6/11/2020
Job #:

Line	Ver	Operation	Description	Qty	Extended Price $	Part Type	Labor	Type	Paint
1	E01		**FRONT BUMPER**						
2	S01	Remove/Replace	O/H front bumper				3.8	Body	
3	S03	Remove/Replace	Grille			OEM	0.0	Body	
4	S02	Remove/Replace	Bumper cover	1	1,697.87T	OEM	0.0	Body	2.0
5	S02	Remove/Replace	Strip retaining upper	1	93.25T	OEM	0.0	Body	
6	S02	Remove/Replace	RT Upper seal side	1	40.72T	OEM	0.0	Body	
7	S02	Remove/Replace	LT Upper seal side	1	46.50T	OEM	0.0	Body	
8	S02	Remove/Replace	Strip center	1	44.71T	OEM	0.0	Body	
9	S02	Remove/Replace	RT Protect bar	1	32.79T	OEM	0.0	Body	
10	S02	Remove/Replace	Strip rivet	3	3.24T	OEM	0.0	Body	
11	S02	Remove/Replace	LT Protect bar	1	32.79T	OEM	0.0	Body	
12	S02	Remove/Replace	RT Protect bar cap	1	4.41T	OEM	0.0	Body	
13	S04	Remove/Replace	Bumper to liner bracket nut	4	2.44T	OEM			
14	S04	Remove/Replace	freight	1	5.00T	Other			
15	S04	Remove/Replace	Bumper to liner bracket RT	1	14.65T	OEM			
16	S04	Remove/Replace	Bumper to liner bracket LT	1	14.65T	OEM			
17	S04	Remove/Replace	Bumper to liner screw	4	4.32T	OEM			
18	S02	Remove/Replace	LT Protect bar cap	1	5.27T	OEM			
19	S02	Blend	RT Lower cover				0.0	Body	
20	S02	Blend	LT Lower cover						0.3
21	E01		**FRONT LAMPS**						0.3
22	E01	Remove/Install	RT Headlamp assy w/o Litronic lamps				0.4	Body	
23	E01	Remove/Install	LT Headlamp assy w/o Litronic lamps				0.4	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 904647

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

24	E01	Remove/Install	RT Fog lamp assy				0.0 Body	
25	E01	Remove/Install	LT Fog lamp assy				0.0 Body	
26	E01	Remove/Replace	Aim headlamps			OEM	0.5 Body	
27	E01	Remove/Replace	RT Hose adapter	1	4.40T	OEM		
28	E01	Remove/Replace	LT Hose adapter	1	4.40T	OEM		
29	S02	Remove/Replace	RT Nozzle	1	65.0	[redacted]	0.3 Body	
30	S02	Remove/Replace	LT Nozzle	[redacted]			0.3 Body	
31	E01		**HOOD**					
32	E01	Repair	[redacted]				6.0 Body	2.5
33	S01		Overlap Major Non-Adj. Panel					(0.2)
34	E01	Remove/Replace	Emblem	1	142.27T	OEM	0.2 Body	
35	S02	Remove/Replace	Emblem gasket	1	8.90T	OEM		
36	E01	Remove/Install	Weatherstrip				0.5 Body	
37	E01	Remove/Install	R&I hood assy				0.8 Body	
38	E01		**FENDER**					
39	E01	Repair	RT Fender w/o turbo, 4S				4.0 Body	2.0
40	E01		Overlap Major Adj. Panel					(0.4)
41	S02	Remove/Replace	RT Rear seal	1	34.66T	OEM		
42	S02	Remove/Replace	LT Rear seal	1	34.66T	OEM		
43	E01	Remove/Install	Fuel door				0.3 Body	
44	E01	Remove/Install	RT R&I fender assy				3.3 Body	
45	S01	Remove/Install	Deduct for Overlap				(0.5) Body	
46	E01	Remove/Install	LT R&I fender assy				3.3 Body	
47	S01	Remove/Install	Deduct for Overlap				(0.5) Body	
48	E01	Repair	Filler pocket				2.0 Body	
49	E01	Repair	Fuel door				1.0 Body	0.3
50	E01	Repair	LT Fender w/o turbo, 4S				8.0 Body	2.0
51	E01		Overlap Major Adj. Panel					(0.4)
52	S02	Remove/Replace	LT Fender liner rear	1	150.74T	OEM	0.5 Body	
53	E01	Remove/Install	RT Reinforcement				0.2 Body	
54	E01	Remove/Install	LT Reinforcement				0.2 Body	
55	E01	Remove/Install	RT Fender liner rear				0.5 Body	
56	E01		**EXHAUST SYSTEM**					
57	S03	Remove/Replace	RT Tailpipe			OEM		
58	S03	Remove/Replace	RT Muffler			OEM		
59	E01	Remove/Install	RT Heat shield muffler				0.3 Body	
60	E01		**WHEELS**					
61	S03	Remove/Replace	RT/Front Wheel rear 18x10, 4S			OEM		
62	E01	Remove/Install	LT/Front R&I wheel				0.1 Body	
63	E01	Remove/Install	RT/Front R&I wheel				0.1 Body	
64	S03	Remove/Replace	LT/Rear Wheel rear 18x10, 4S			OEM		
65	E01		**WINDSHIELD**					

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Number: 904647

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

66	S02	Remove/Replace	RT Nozzle	1	52.87T	OEM	0.3	Body	
67	S04	Remove/Replace	freight	1	5.00	Other			
68	S02	Remove/Replace	LT Nozzle	1	49.56T	OEM	0.3	Body	
69	S04	Remove/Replace	Windshield gasket outer	1	109.50T	OEM	0.0	Body	
70	E01	Remove/Install	RT Wiper arm				0.0	Body	
71	S02	Remove/Replace	Windshield Porsche tinted	1	1,418.04T	Glass	3.8	Body	
72	E01	Remove/Install	LT Wiper arm				0.0	Body	
73	S02	Remove/Replace	Windshield gasket inner	1	83.70T	OEM	0.0	Body	
74	S02	Remove/Replace	Cap	2	7.86T	OEM			
75	E01		**COWL**						
76	E01	Remove/Install	Air vent grille				0.0	Body	
77	E01	Remove/Install	Frame				0.3	Body	
78	E01	Repair	Upper cover				1.0	Body	0.6
79	S02		Overlap Minor Panel						(0.2)
80	E01		**INSTRUMENT PANEL**						
81	E01	Remove/Install	Speaker door w/standard system tweeter				0.3	Body	
82	E01	Remove/Install	Speaker door w/standard system tweeter				0.3	Body	
83	E01	Repair	Fix Speaker Wire				1.0	Body	
84	E01		**ROOF**						
85	E01	Repair	Roof assy w/o turbo w/o sunroof				3.0	Body	2.5
86	E01		Overlap Major Adj. Panel						(0.4)
87	E01	Remove/Install	Rpl sunroof				3.5	Body	
88	E01	Remove/Install	Outer panel				0.0	Body	
89	S03	Remove/Replace	Rear seal front	1	48.36T	OEM	0.0	Body	
90	S02	Remove/Replace	Weatherstrip around frame	1	74.96T	OEM	0.0	Body	
91	E01	Remove/Install	Headliner w/o sunroof				8.5	Body	
92	S02	Blend	Outer panel						0.8
93	S02	Remove/Replace	Front guide	1	62.94T	OEM	0.0	Body	
94	E01		**PILLARS, ROCKER & FLOOR**						
95	S02	Remove/Replace	RT Rocker molding w/o turbo	1	668.42T	OEM	0.4	Body	
96	S02	Remove/Replace	LT Rocker molding w/o turbo	1	668.42T	OEM	0.4	Body	
97	E01	Remove/Replace	RT End support retainer nut	4	1.12T	OEM			
98	E01	Remove/Replace	LT End support retainer nut	4	1.12T	OEM			
99	S02	Remove/Replace	ROCKER MOLDING U CLIP	7	66.64T	OEM			
100	E01	Repair	LT Outer rocker w/o turbo				10.0	Body	1.0
101	E01		Overlap Major Adj. Panel						(0.4)
102	E01	Blend	RT Outer rocker w/o turbo						0.5
103	S02	Remove/Replace	RT End support w/o turbo	2	10.12T	OEM			
104	S02	Remove/Replace	LT End support w/o turbo	2	10.12T	OEM			
105	S02	Remove/Replace	Floor cover	1	378.70T	OEM	0.3	Body	
106	E01		**DOOR**						

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 904647

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

107	E01	Repair	LT Door shell				4.0	Body	2.3
108	E01		Overlap Major Adj. Panel						(0.4)
109	E01	Remove/Install	RT Belt molding coupe				0.5	Body	
110	E01	Remove/Install	LT Belt molding coupe				0.5	Body	
111	E01	Remove/Install	RT Window frame				1.0	Body	
112	E01	Remove/Install	LT Window frame				1.0	Body	
113	E01	Remove/Install	RT Vent glass Porsche				0.8	Body	
114	E01	Remove/Install	LT Vent glass Porsche				0.8	Body	
115	E01	Remove/Install	RT Door glass Porsche				1.2	Body	
116	E01	Remove/Install	LT Door glass Porsche				1.2	Body	
117	E01	Remove/Install	RT Handle, outside				0.5	Body	
118	E01	Remove/Install	LT Handle, outside				0.5	Body	
119	E01	Remove/Install	RT R&I trim panel				1.0	Body	
120	E01	Repair	Fabricate watershield				1.0	Body	
121	E01	Remove/Install	LT R&I trim panel				1.0	Body	
122	E01	Remove/Install	O/H mirror assy lt				1.0	Body	
123	E01	Remove/Install	LT Housing				0.0	Body	
124	E01	Repair	LT Housing				2.0	Body	
125	E01	Remove/Install	LT Glass				0.0	Body	
126	E01	Remove/Install	LT Reinf plate				0.0	Body	
127	E01	Remove/Install	LT Mount arm				0.0	Body	
128	S01	Repair	LT Handle, outside				1.0	Body	0.5
129	E01	Repair	RT Door shell				1.0	Body	2.3
130	E01		Overlap Major Adj. Panel						(0.4)
131	E01	Remove/Install	RT Housing				0.5	Body	
132	E01	Remove/Install	RT R&I door assy				1.7	Body	
133	E01	Remove/Install	LT R&I door assy				1.7	Body	
134	E01		**BACK GLASS**						
135	S02	Remove/Replace	Back glass gasket outer	1	141.44T	OEM	0.8	Body	
136	E01		**QUARTER PANEL**						
137	S01	Repair	Set-up for floor pull				2.0	Body	
138	S01	Repair	Pre-pull - LT quarter				1.5	Body	
139	S01	Repair	LT Quarter panel w/o turbo				9.0	Body	2.3
140	E01		Overlap Major Adj. Panel						(0.4)
141	S01	Repair	Pre-pull - RT quarter				2.5	Body	
142	S04	Remove/Replace	Freight	1	5.00	Other			
143	S01	Repair	RT Quarter panel w/o turbo				14.0	Body	2.3
144	E01		Overlap Major Adj. Panel						(0.4)
145	S04	Remove/Replace	RT Stone guard large w/o turbo & 4S clear	1	125.86T	OEM	0.4	Body	
146	S02	Remove/Replace	LT Stone guard large w/o turbo & 4S clear	1	125.86T	OEM	0.4	Body	
147	E01	Remove/Install	RT Qtr glass Porsche				1.5	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 904647

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

148	E01	Remove/Install	LT Qtr glass Porsche				1.5	Body	
149	S02	Remove/Replace	LT Belt molding	1	121.24T	OEM	0.4	Body	
150	S02	Remove/Replace	RT Belt molding	1	121.24T	OEM	0.4	Body	
151	E01	Remove/Install	RT Upper cover leatherette				0.3	Body	
152	E01	Remove/Install	LT Upper cover leatherette				0.3	Body	
153	E01	Remove/Install	RT Upper pillar				0.3	Body	
154	E01	Remove/Install	LT Upper pillar				0.3	Body	
155	S02	Remove/Replace	RT Wheelhouse liner rear section w/o turbo & 4S	1	150.74T	OEM	0.3	Body	
156	E01		**ENGINE LID**						
157	S02	Remove/Replace	Wire retainer	10	9.70T	OEM			
158	S04	Remove/Replace	Freight	1	5.00	Other			
159	E01	Repair	Engine lid				2.0	Body	1.5
160	E01		Overlap Major Adj. Panel						(0.4)
161	E01	Remove/Install	Outer panel				0.7	Body	
162	E01	Remove/Install	Grille				1.2	Body	
163	S02	Remove/Replace	Emblem "4S"	1	44.22T	OEM	0.2	Body	
164	S02	Remove/Replace	Emblem "Carrera" chrome	1	66.73T	OEM	0.2	Body	
165	E01	Remove/Install	R&I lid				1.0	Body	
166	S02	Remove/Replace	Emblem "4"	1	24.02T	OEM	0.2	Body	
167	E01		**REAR LAMPS**						
168	E01	Remove/Install	High mount lamp				0.3	Body	
169	E01	Remove/Install	Combo lamp assy				0.6	Body	
170	E01	Remove/Install	Upper trim				0.3	Body	
171	E01	Remove/Install	RT Combo lamp assy				0.4	Body	
172	E01	Remove/Install	LT Combo lamp assy				0.4	Body	
173	E01		**REAR BUMPER**						
174	S01	Remove/Replace	O/H rear bumper				3.0	Body	
175	S03	Remove/Replace	RT Strip seal w/o turbo & 4S	1	16.79T	OEM	0.0	Body	
176	S02	Remove/Replace	Protector center w/o turbo & 4S	1	265.78T	OEM	0.3	Body	
177	S02	Remove/Replace	Cover w/o turbo, 4S	1	1,570.21T	OEM	0.0	Body	2.0
178	S01		Overlap Major Non-Adj. Panel						(0.2)
179	E01		Clear Coat						2.5
180	E01	Refinish	Car Cover						0.2
181	E01	Refinish	Corrosion Protection						0.3
182	S01		Flex Additive	2	12.00T	Other			
183	E01	Sublet	Hazardous Waste Disposal Fee	1	5.00	Other			
184	E01	Refinish	Tint Color						0.5
185	E01	Sublet	Tire Mount and Balance	1	25.00	Other			
186	S01	Refinish	Wet/ Dry Sand, Rub Out and Buff to match factory finish						7.0
187	E01	Remove/Install	Reinforcement w/o turbo & 4S				0.0	Body	
188	S04	Remove/Replace	Strip lower w/o turbo & 4S	1	65.60T	OEM	0.0	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 904647

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline Maroon

189	S02	Remove/Replace	Center support	1	60.60T	OEM	0.0	Body
190	S02	Remove/Replace	Protector rivet	8	7.92T	OEM		
191	S04	Remove/Replace	Strip rivet	8	4.88T	OEM	0.0	Body
192	S02	Remove/Replace	Side support rivet	12	25.68T	OEM		
193	S02	Remove/Replace	Center support rivet	6	12.84T	OEM		
194	E01	Repair	Mask Rear Bumper texture				0.5	Body
195	E01	Repair	Mask Openings				1.5	Body
196	S03	Remove/Replace	LT Strip seal w/o turbo & 4S	1	16.79T	OEM	0.0	Body
197	S02	Remove/Replace	Glass Urethane Kit	1	30.00T	A/M		
198	S02	Remove/Replace	LT Heat deflector w/turbo	1	75.70T	OEM		
199	S02	Remove/Replace	RT Heat deflector w/turbo	1	75.70T	OEM		
200	S03	Remove/Replace	Bottom bumper retainer	1	47.84T	OEM	0.0	Body
201	S04	Remove/Replace	Freight	1	25.00	Other		
202	S02	Remove/Replace	Heat deflector rivet	6	6.84T	OEM		
203	S02	Remove/Replace	Heat deflector clamp	6	6.48T	OEM		

Estimate Totals	Discount $	Markup $	Rate $	Total Hours	Total $
Parts					9,537.83
Sublet/Miscellaneous					30.00
Labor, Body			62.00	142.0	8,804.00
Labor, Refinish			62.00	34.3	2,126.60
Material, Paint					1,537.20
Subtotal					**22,035.63**

JeppesenImports
7700 Quattro Drive
Chanhassen, MN 55317
952-934-5511

INVOICE FOR:

Millrace MOTOR CLUB

Vehicle	1996 Porsche 993 Carrera
License	663126
VIN	WPOAA2992TS321853
Mileage	125,234

Parts:	119.50
Tax:	10.78
Labor:	175.00
Misc:	
Environmental Charge:	8.75
TOTAL:	**$314.03**

Invoice# **10089**

Customer # **2996**

Date **5/13/2026**


LABOR	AMT
Change Oil & Filter(s)	
	175.00

P/N	QTY	PARTS DESCRIPTION	AMT	TOTAL AMT
993-107-203-05	1	Oil Filter		0.00
993-207-201-03	1	Oil Filter		0.00
Lm 2024	10Ltr	Synthetic Motor Oil	11.95	119.50

Comments

QUALITY, ISN'T EXPENSIVE..... IT'S PRICELESS !!!

Customer Copy



AUDI PORSCHE RUF

JeppesenImports
7700 Quattro Drive
Chanhassen, MN 55317
952-934-5511

INVOICE FOR:

Millrace
MOTOR CLUB

Vehicle	1996 Porsche 993 Carrera
License	663126
VIN	WPOAA2992TS321853
Mileage	123,363

Parts:	155.45
Tax:	14.03
Labor:	175.00
Misc:	
Environmental Charge:	8.75
TOTAL:	***$353.23***


Invoice# 9766
Customer # 2996
Date 4/23/2025

LABOR	AMT
Change Oil & Filter(s)	
	175.00
Note:	
Rear Tires At Wear Bars.	
Tires Are 9&10 Years Old.	

P/N	QTY	PARTS DESCRIPTION	AMT	TOTAL AMT
993-107-203-05	1	Oil Filter	24.65	24.65
993-207-201-03	1	Oil Filter	21.30	21.30
Lm 2024	10Ltr	Synthetic Motor Oil	10.95	109.50

Comments

QUALITY, ISN'T EXPENSIVE..... IT'S PRICELESS !!!



LaMettry's®
Collision, Glass and More!

LaMettry's Collision- Chanhassen

"Every Customer Leaves with a Smile"
1650 Motorplex Court, Chanhassen, MN 55317
Phone: (952) 843-4778

Workfile ID: 1436c631
PartsShare: 7Zyqzd

Final Bill

RO Number: 911066

Customer:

Millrace MOTOR CLUB

Insurance: SELF PAY
Adjuster:
Phone:
Claim:
Loss Date:
Deductible:

Estimator: Allen Foner
Create Date: 6/18/2024

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline burgundy

VIN:	WP0AA2992TS321853	Interior Color:		Mileage In:	Vehicle Out: 6/28/2024
License:	663126	Exterior Color:	burgundy	Mileage Out:	
State:	MN	Production Date:		Condition:	Job #: ijp - ok

Line	Ver	Operation	Description	Qty	Extended Price $	Part Type	Labor	Type	Paint
1	E01		**ROOF**						
2	E01	Remove/Install	Rpl sunroof				3.5	Body	
3	E01	Remove/Install	Outer panel				0.0	Body	
4	S01	Remove/Replace	Weatherstrip around frame	1	96.03T	OEM	0.0	Body	
5	S01	Repair	Outer panel				3.0	Body	1.5
6	E01		Add for Clear Coat						0.6
7	E01	Remove/Replace	Rear seal front	1	52.18T	OEM	0.0	Body	
8	E01	Remove/Replace	Rear seal rear	1	76.83T	OEM	0.0	Body	
9	E01	Refinish	color tint						0.5
10	E01	Sublet	Hazardous Waste Disposal Fee	1	12.00	Other			
11	S01		Freight @ cost - Invoice# 247	1	20.00T	Other			

Estimate Totals	Discount $	Markup $	Rate $	Total Hours	Total $
Parts					245.04
Labor, Body	(45.50)		70.00	6.5	409.50
Labor, Refinish	(18.20)		70.00	2.6	163.80
Material, Paint					135.20
Material, Shop			2.00	3.0	6.00
Miscellaneous					12.00
Subtotal					**971.54**
Sales Tax					32.35
Grand Total					**1,003.89**
Net Total					**1,003.89**

Estimate Version	Total $
Original	875.84

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Number: 911066

1996 PORS 911 Carrera 4 S 2D CPE 6-3.6L Gasoline burgundy

Supplement S01	128.05
Insurance Total $:	0.00
Received from Insurance $:	0.00
Balance due from Insurance $:	0.00
Customer Total $:	1,003.89
Received from Customer $:	0.00
Balance due from Customer $:	1,003.89

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

Work Order #2852

05/31/2023

Millrace MOTOR CLUB

1996 Porsche 911
WP0AA2992TS321853
Engine: 3.6L H6 (A) GAS FI
Plate: 664LVE
Fleet #: 4 WHEEL DRIVE
Odometer In:
Odometer Out:

Advisor: Ben Roberts
Technician: Vince Scatena

GRAND TOTAL: $2,339.86
✔ PAID

SERVICES

1 Remove and Replace Front Strut Cartridge - Both

SUBTOTAL: $2,080.47

LABOR

PARTS	QTY
Strut - Bilstein B6 Performance	1.0
Strut - Bilstein B6 Performance	1.0

2 2 Wheel Alignment-NEW

SUBTOTAL: $109.99

LABOR

Adjust tire pressures to factory specifications
Measure and record pre-alignment condition
Inspect steering and suspension components
Perform alignment adjustments to factory specifications
Measure and record post-alignment condition
Center steering wheel; calibrate zero point position (as needed)

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

GRAND TOTAL: $2,339.86

Total Labor: $717.99
Total Parts: $1,472.47
Total Fees: $0.00
Total Sublets: $0.00
Shop Supplies: $35.90
Sales Tax: $113.50

✔ PAID

04:16 PM
$2,339.86
:-xxxx-xx01
)Z_bbSmrl"

Millrace
MOTOR CLUB

Signed:



Terms of Service:

1. "YES, DO THIS WORK"
I hereby authorize the corresponding service to be done along with the necessary materials.
2. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"
Werks Automotive staff may operate my vehicle for the purpose of testing, inspection, and delivery.
3. "NO PAYMENT, NO KEYS"
An express lien is acknowledged on my vehicle to secure the amount of services thereto.
4. "ONLINE COMMUNICATION OK"
I welcome email from Werks Automotive as a means of receiving copies of my estimate, work order, and invoice.
5. "HERE'S MY SIGNATURE"
I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these five terms.

Authorization:

Ref1# 92[illegible]

Ref2# 7082280

Purchase Order# 705749

**** PACKING LIST ***** 12/08/13

FEDEX 3 3rd Day

Ship Date: 12/09/13

From:

PELICAN PARTS
1600 240TH STREET

HARBOR CITY CA 90710-1311

To:

Millrace
MOTOR CLUB

1

MN 55347

161604

Tel: (310)626-8765

Itm	Ord.	Ship	Part Number	Description
1	1	1	993-347-088-01	Air Bag Retaining Frame

**** PACKING LIST ***** 3/19/14

From:

PELICAN PARTS
1600 240TH STREET

HARBOR CITY CA 90710-1311

To:



ail

MN 55347

FEDEX G Ground

Ship Date: 3/19/14

Page:
13411

Tel: (310)626-876

Itm	Ord.	Ship		Part Number	Description
2	1	1	76	993-615-227-01	Relay
1	1	1	~~127~~	993-512-121-00	Grille Wall

9

1.02

****** PACKING LIST ******* 3/19/14

From:

PELICAN PARTS
1600 240TH STREET

HARBOR CITY CA 90710-1311

To:

Millrace
MOTOR CLUB

ail

MN 55347

FEDEX G Ground

Ship Date: 3/19/14

Page:
13411

Tel: (310)626-876

Itm	Ord.	Ship		Part Number	Description
2	1	1	76	993-615-227-01	Relay
1	1	1	~~187~~	993-512-121-00	Grille Wall

9

1.02

COURTNEY TRUCK SERVICE

14205 W 62ND ST
EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Repair Order # **0055476**
Date : 8/13/2014
Page 1 of 1
Center : 8

Custc
Add
C
WK : (952) -
Millrace MOTOR CLUB
-
47-
Ext : CELL
Ext :

Vehicle : 1996 PORS 911 SERIES
License : 664LVE **PRDT :** 01/96
VIN : WP0AA2992TS321853
Fleet #:
Engine : 6-3600 3.6L SOHC **Trans :** STD
Mileage : 97893 **COLR :** BURGAND

Parts

Quan	Part Number	Description	Price
0.50	BF	DOT 4 BRAKE FLUID-C	8.75
2.00	993 612 365 01	BRAKE PAD SENSOR EI	28.48

		Payments:	
	AMERIC, on 08/13/14	**********1014	$431.16
	Auth#:532727		

Labor

Op	Tech	Description	Time	Charge
		Service Requests:		
		1.BLEED BRAKES. SOFT PEDAL. SEES FLUID LEAK IN OVERFLOW VICINITY.		
		2.INSTALL CUSTOMER'S OEM BRAKE PADS.		
BRK010	AS	REMOVE AND REPLACE FRONT BRAKE PADS WITH CUSTOMER SUPPLIED PART. CLEAN AND LUBE CALIPER SLIDES. DID NOT HAVE NEW SENSORS AT TIME OF SERVICE. BYPASSED SENSORS UNTIL NEST WEEK WHEN CUSTOMER COMES BACK.		148.12
BRK020	AS	REMOVE AND REPLACE REAR BRAKE PADS WITH CUSTOMER SUPPLIED PARTS. INSTALL NEW PAD SENSORS. CLEAN AND LUBE CALIPER SLIDES.		160.46
BRK045	AS	BLEED & FLUSH BRAKING SYSTEM		56.72

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Labor :	$365.30
Parts :	$37.23
Sublet :	$0.00
Other Fees :	$0.00
Supply Charg	$24.16
Subtotal :	$426.69
Sales Tax :	$4.47
Paid By : AMERICAN EXPRES	
Total :	$431.16
Pay Ref :	
Paid :	$431.16
Due :	$0.00

CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Invoice #0058578 11/25/2015 8:21 am

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 105115
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : C4S

Your Service Writer Today Is: MICK SOBTZAK Center: RETAIL

Service Requests:
BALANCE WHEELS.

Category Summary	Parts	Labor	Job Total
TIRES	$0.00	$60.00	$60.00

Technician	Service Description	Parts	Labor	Job Total
AS	**BALANCE TIRES**		60.00	60.00

Payments:
AMERICAN EXPRES, $65.36, on 11/25/15
CardNo: [********1014], AuthorizationNo: [561504]**

Repair Order Notes

*****TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.**

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

****TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.**

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$0.00
TOTAL LABOR	$60.00
SUBLET	$0.00
Supply Charg	$5.00
SUBTOTAL	$65.00
OTHER FEES	$0.00
SALES TAX	$0.36
INVOICE TOTAL	**$65.36**
PAID	$65.36
DUE	$0.00

Imola Motorsports, Inc.

2980 Empire Lane
Plymouth MN, 55447
Phone: 763-205-2561 Fax: 763-208-6930

04/15/2015
Invoice # **26712**

Millrace MOTOR CLUB

PAID

1996 Porsche 911

License: VIN: WP0AA2992T5321853

Description Of Services

Mount and balance two low profile tires.

Part Number	Description	Quantity	Sale	Extended
103301	Bridgestone Potenza S-04 Pole Position 285/30R18	2.00	$260.00	$520.00
993 361 073 00	Tire Valve Stem	1.00	$19.46	$19.46

Labor: $60.00 **Parts:** $539.46 **Sublet:**$0.00 **Job Total:** $599.46

Tire Disposal Fee - $3.75/ea

Labor: $0.00 **Parts:** $0.00 **Sublet:**$7.50 **Job Total:** $7.50

SHIPPING

SHIPPING - GROUND

Labor: $0.00 **Parts:** $0.00 **Sublet:**$32.67 **Job Total:** $32.67

Remove Tire from one wheel

Labor: $24.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $24.00

Service Advisor: Herrmann, Mark
Technician(s): Fuller, Liam; Luterbach, Ryan

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.
All Imola Motorsports factory replacement parts and labor carry a 24 month/24,000 mile warranty. Consumable part items such as brakes, tires and clutches etc are evaluated on a case by case basis. Imola Motorsports parts warranty does NOT apply on customer supplied parts.

I acknowledge that some aftermarket work performed by Imola Motorsports, may further enhance the performance of my vehicle. I hereby release Imola Motorsports from any actions, claims, loss, liability, damage or costs, occurring in connection with operating my vehicle.

Labor Total:	$84.00
Parts Total:	$539.46
Sublet Total:	$40.17
Shop Sup.:	$5.22
HazMat:	$0.00
Sub Total:	$668.85
Tax Total:	$39.25
Grand Total:	$708.10
Balance Due:	**$0.00**

VISA MasterCard DISCOVER AMERICAN EXPRESS

SIGNATURE.....**Date**.....

Payment(s)

4/2/2015 9:54:33AM	$500.00	American Express
4/15/2015 2:13:08PM	$208.10	American Express

YouTube

California Chrome Wheel, Inc.

Shipping: 24850 Ave Rockefeller, Valencia, CA 91355
Billing: P.O. Box 802936, Santa Clarita, CA 91380-2936
Tel: (661)-294-0170 Fax: (661) 294-0104

WWW.CALCHROME.COM
WWW.MARCELLINOWHEELS.COM

Invoice

DATE	INVOICE #
3/13/2015	83167

*See Website - Terms/Conditions/Warranty

BILL TO	SHIP TO
Millrace MOTOR CLUB	tigewill@yahoo.com

REP	SHIP DATE	VIA	DRIVER
BCR	3/31/2015	FED EX	BLAINE

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
CUST CORES PORSCHE	CUSTOMER CORES FOR PROCESSING - REF. # C15-5705 YEAR: 1996 MODEL: PORSCHE 911 C4S WHEEL SIZE: 18X10.0" +40MM WHEEL DESC. / H #: TURBO LOOK TECHNOLOGY SWEPT 5-SPOKE (HOLLOW SPOKES) 993.382.140.00 TIRES: NONE CUST. P/U REC #: NO CAP. ***PLEASE PLUG VALVE HOLE BEFORE PLATING*** (HOLLOW SPOKES)	1	0.00	0.00
CHROME ELECTROPLA...	CHROME ELECTROPLATE FINISH APPLIED TO 18" ALUMINUM ALLOY WHEEL	1	150.00	150.00
FEDEX FREIGHT RESID...	FEDEX FREIGHT HOME DELIVERY	1	40.00	40.00
PAY PAL FEES	THESE FEES ARE CHARGED TO CALIFORNIA CHROME WHEEL INC. FOR PROCESSING YOUR PAYMENT VIA PAYPAL ** YOU ARE NOT BEING CHARGED THIS FEE ** INV# 83167 TRANSACTION ID # 56N231273A805560L Total $190.00, Fee -$4.48, Net $185.52, 03-13-2015		-4.48	-4.48

Millrace MOTOR CLUB

Total: $185.52

Thank you for purchasing from California Chrome Wheel Inc / MarcellinoWheels.com. This transaction consumates an agreement by you the purchaser to the terms, conditions and warranty policy detailed on our website at www.calchrome.com.

California Chrome Wheel, Inc.

Shipping: 24850 Ave Rockefeller, Valencia, CA 91355
Billing: P.O. Box 802936, Santa Clarita, CA 91380-2936
Tel: (661)-294-0170 Fax: (661) 294-0104

WWW.CALCHROME.COM
WWW.MARCELLINOWHEELS.COM

Invoice

DATE	INVOICE #
3/13/2015	83167

*See Website - Terms/Conditions/Warranty

BILL TO	SHIP TO
Millrace MOTOR CLUB	Millrace MOTOR CLUB

REP	SHIP DATE	VIA	DRIVER
BCR	3/31/2015	FED EX	BLAINE

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
CUST CORES PORSCHE	CUSTOMER CORES FOR PROCESSING - REF. # C15-5705 YEAR: 1996 MODEL: PORSCHE 911 C4S WHEEL SIZE: 18X10.0" +40MM WHEEL DESC. / H #: TURBO LOOK TECHNOLOGY SWEPT 5-SPOKE (HOLLOW SPOKES) 993.382.140.00 TIRES: NONE CUST. P/U REC #: NO CAP. ***PLEASE PLUG VALVE HOLE BEFORE PLATING*** (HOLLOW SPOKES)	1	0.00	0.00
CHROME ELECTROPLA...	CHROME ELECTROPLATE FINISH APPLIED TO 18" ALUMINUM ALLOY WHEEL	1	150.00	150.00
FEDEX FREIGHT RESID...	FEDEX FREIGHT HOME DELIVERY	1	40.00	40.00
PAY PAL FEES	THESE FEES ARE CHARGED TO CALIFORNIA CHROME WHEEL INC. FOR PROCESSING YOUR PAYMENT VIA PAYPAL ** YOU ARE NOT BEING CHARGED THIS FEE ** INV# 83167 TRANSACTION ID # 56N231273A805560L Total $190.00, Fee -$4.48, Net $185.52, 03-13-2015		-4.48	-4.48

Total: $185.52

Thank you fo ...llinoWheels.com. This transaction consumates an agre... ...warranty policy detailed on our website at www.calchrome.com.

Imola Motorsports, Inc.
2980 Empire Lane
Plymouth MN, 55447
Phone: 763-205-2561 Fax: 763-208-6930

06/12/2014
Invoice # **23423**

Millrace MOTOR CLUB

PAID

1996 Porsche 911

License:

Odometer Out: 96004
VIN: WP0AA2992T5321853

Description Of Services

Customer is getting a shake between 60-70mph. Rebalance wheels (standard)

Labor: $50.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $50.00

Service Advisor: Herrmann, Mark
Technician(s): Luterbach, Ryan

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

All Imola Motorsports factory replacement parts and labor carry a 12 month/12,000 mile warranty. Consumable part items such as brakes, tires and clutches etc are evaluated on a case by case basis. Imola Motorsports parts warranty does NOT apply on customer supplied parts.

I acknowledge that some aftermarket work performed by Imola Motorsports, may further enhance the performance of my vehicle. I hereby release Imola Motorsports from any actions, claims, loss, liability, damage or costs, occurring in connection with operating my vehicle.

Labor Total:	$50.00
Parts Total:	$0.00
Sublet Total:	$0.00
Shop Sup.:	$2.10
HazMat:	$0.50
Sub Total:	$52.60
Tax Total:	$0.00
Grand Total:	$52.60
Balance Due:	**$0.00**

SIGNATURE..... **Date**.....

Payment(s)
6/12/2014 1:41:53PM $52.60 American Express

COURTNEY TRUCK SERVICE

14205 W 62ND ST
EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Repair Order # 0055502
Date : 8/18/2014
Page 1 of 1
Center : 8

Custc
Add
C
WK : (952) -

Millrace MOTOR CLUB

-
47-
Ext : CELL
Ext :

Vehicle : 1996 PORS 911 SERIES
License : 664LVE **PRDT :** 01/96
VIN : WP0AA2992TS321853
Fleet #:
Engine : 6-3600 3.6L SOHC **Trans :** STD
Mileage : 98031 **COLR :** BURGAND

Parts

Quan	Part Number	Description	Price
2.00	99361236801	SENSOR, BRAKE PAD	28.36

		Payments:	
		[redacted]	$38.47

Labor

Op	Tech	Description	Time	Charge
BRK0	AS	INSTALL FRONT BRAKE PAD SENSORS.		0.00
		NO CHARGE LABOR, REPLACED PADS LAST WEEK,		
		DIDN'T HAVE CORRECT SENSORS.		

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Labor :	$0.00
Parts :	$28.36
Sublet :	$0.00
Other Fees :	$0.00
Supply Charg	$7.50
Subtotal :	$35.86
Sales Tax :	$2.61
Paid By : ~~MSTR CHARG VISA~~	
Total :	$38.47
Pay Ref :	
Paid :	$38.47
Due :	$0.00

Am Exp

CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
DOWNLOAD OUR MOBILE APP ON APPLE OR ANDR

Invoice #0062197 6/19/2017 3:13 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 111400
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : C4S

Your Service Writer Today Is: MICK SOBTZAK Center: RETAIL

Service Requests:
VALVE COVER GASKETS STEERING GEAR
RANDOM CODE FOR SAI BANK 4-5-6, P0491? ANY EASY FIX?
ALIGN

Category Summary	Parts	Labor	Job Total
ALIGNMENT	$0.00	$159.99	$159.99
CHASSIS AND STEERING	$1,767.20	$580.65	$2,347.85
ENGINE	$40.82	$545.10	$585.92

Technician	Service Description	Parts	Labor	Job Total
AS	REMOVE AND REPLACE LOWER VALVE COVER GASKETS	40.82	545.10	585.92

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	993 105 135 02	VALVE COVER GASKET-L	20.41	2	40.82

Technician	Service Description	Parts	Labor	Job Total
AS	REMOVE AND REPLACE RACK AND PINION STEERING ASSEMBLY. REFILL FLUID AND BLEED.	1767.20	580.65	2347.85

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	993 347 011X	STEERING RACK	1686.25	1	1686.25
S		FREIGHT	75.00	1	75.00
S	ATF BULK	TRANSMAX SYNTH ATF BULK	5.95	1	5.95

Technician	Service Description	Parts	Labor	Job Total
AS	FOUR WHEEL ALIGNMENT INCLUDES CASTER,CAMBER AND TOE RESET		159.99	159.99

Payments:
MSTR CHARG VISA, $3277.74, on 06/19/17
CardNo: [********1755], AuthorizationNo: [41108D]**

Repair Order Notes

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ Date: _____

TOTAL PARTS	$1,733.02
TOTAL LABOR	$1,285.74
SUBLET	$0.00
Supply Charg	$53.98
SUBTOTAL	$3,147.74
OTHER FEES	$75.00
SALES TAX	$130.00
INVOICE TOTAL	**$3,277.74**
PAID	$3,277.74
DUE	$0.00

Millrace
MOTOR CLUB

528327

INVOICE

PAGE 1

PORSCHE OF MINNEAPOLIS

9191 Wayzata Boulevard - Minneapolis, MN 55426
Phone: (763) 744-9191 - Fax: (763) 744-9154

PORSCHE

SERVICE ADVISOR: 670 JONATHAN BEYER

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
MAROON	96	PORSCHE C4S	WP0AA2992TS321853		94500/94502	T3547

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN96 IS 01JAN96 DD		01JAN2000	18:00 13DEC13		0.00	CASH	17DEC13

R.O. OPENED	READY	OPTIONS:
13:04 13DEC13	15:03 17DEC13	

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
B C/S: customer wants to wait-X-Time didn't allow waiter-too long			
INFO DEFAULT			
160 CP		0.00	0.00
**********			
C BALANCE AND ROTATE TIRES			
PTB REMOVE EXISTING WHEEL WEIGHTS AND RE-BALANCE			
ALL 4 WHEELS.			
160 CPLD		59.95	59.95
1 balanced all winter wheels			
**********			
D PORSCHE 4 WHEEL ALIGNMENT			
PP PORSCHE 4 WHEEL ALIGNMENT			
160 CPLD		225.00	225.00
1 performed 4 wheel alignment			
**********			
E ***** PERFORM COMPLIMENTARY VEHICLE INSPECTION			
QVI DEFAULT			
160 CP		0.00	0.00
**********			
F COMPLIMENTARY CAR WASH			
WASH DEFAULT			
160 CP		0.00	0.00
**********			
G THE BACK RIGHT WHEEL SPACER IS MISSING A NUT. CHECK AND ADVISE			
BR001 REMOVE STRIPPED STUD ON RIGHT REAR WHEEL			
AND INSTALL NEW STUD.			
160 CP		272.00	272.00
1 P904-341-671-00 WHEEL BOLT 45MM	11.94	11.94	11.94
1 R/R RIGHT REAR BRAKE CALIPER, ROTOR AND E-BRAKE SHOES. HEAT UP CROSS THREADED STUD AND REMOVE. INSTALL SOP STUD AND RE-ASSEMBLY E-BRAKE SHOES, ROTOR AND CALIPER. REINSTALL WHEEL AND TEST DRIVE.			
**********			
H** THE HORN DOES NOT SOUND. THE BASKET HAS BEEN REPLACED BUT STILL NO FUNCTION			

OUR REPORT CARD

A score of 10 = PASS, Anything else = FAIL

Thank you for your business. As a customer of Porsche of Minneapolis you are entitled to excellent service. It is our mission to provide that. If your experience was less than excellent please notify your service advisor or the Service Manager, Al Peterson. We would appreciate the opportunity to address your concerns.

Customer Signature

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

ALL PARTS NEW ORIGINAL EQUIPMENT UNLESS OTHERWISE SPECIFIED

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS AJUSTMENT	
SALES TAX	
PLEASE PAY THIS AMOUNT	

SERVICE HOURS: MONDAY - FRIDAY 7:00am - 6:00pm

CUSTOMER COPY

Millrace
MOTOR CLUB

528327

INVOICE

PAGE 2

PORSCHE OF MINNEAPOLIS
9191 Wayzata Boulevard - Minneapolis, MN 55426
Phone: (763) 744-9191 - Fax: (763) 744-9154

PORSCHE

SERVICE ADVISOR: 670 JONATHAN BEYER

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
MAROON	96	PORSCHE C4S	WP0AA2992TS321853		94500/94502	T3547

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN96 IS 01JAN96 DD		01JAN2000	18:00 13DEC13		0.00	CASH	17DEC13

R.O. OPENED	READY	OPTIONS:
13:04 13DEC13	15:03 17DEC13	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	PBULB			CHECK OUT AND REPLACE FUSE FOR HORNS. NOT IN CORRECT LOCATION.	19.95		19.95
		160	CP				

1 replaced fuse that wasnt in the correct spot for horns

****

Online Appt created 2013-12-12
08:51:00am taken by

OUR REPORT CARD

A score of 10 = PASS, Anything else = FAIL

Thank you for your business. As a customer of Porsche of Minneapolis you are entitled to excellent service. It is our mission to provide that. If your experience was less than excellent please notify your service advisor or the Service Manager, Al Peterson. We would appreciate the opportunity to address your concerns.

Customer Signature

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

ALL PARTS NEW ORIGINAL EQUIPMENT UNLESS OTHERWISE SPECIFIED

DESCRIPTION	TOTALS
LABOR AMOUNT	576.90
PARTS AMOUNT	11.94
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	33.86
TOTAL CHARGES	622.70
LESS AJUSTMENT	0.00
SALES TAX	0.87
PLEASE PAY THIS AMOUNT	623.57

- 75.05

= 548.52

SERVICE HOURS: MONDAY - FRIDAY 7:00am - 6:00pm

CUSTOMER COPY

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

Invoice #2847

05/31/2023

Millrace
MOTOR CLUB

1996 Porsche 911
WP0AA2992TS321853
Engine: 3.6L H6 (A) GAS FI
Plate: 664LVE
Fleet #: 4 WHEEL DRIVE
Odometer In:
Odometer Out: 120315

Advisor: Ben Roberts
Technician: Tanner Farrell

GRAND TOTAL: $212.60
✔ PAID

SERVICES

1 Porsche Lube and Oil Change - SYNTHETIC

SUBTOTAL: $196.05

LABOR

Drain and fill engine oil
Replace engine oil filter
Replace drain plug gasket
Lubricate suspension components as needed
Set tire pressures to specification
Perform multipoint inspection

PARTS	QTY
SYNTHETIC OIL	11.0
Oil Filter Spin-On	1.0

HAZMATS & FEES	QTY
	1.0

2 Check Belt Squeak

SUBTOTAL: $0.00

Check all belts. Squeak on start up

3 Check for Leak From Right Front of Vehicle

SUBTOTAL: $0.00

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

Invo

P
05/3

FINDINGS

Replace AC belt

Written by Tanner Farrell at 05/31/2023 03:16 PM


Oil leaks
Front right strut leaking

Written by Tanner Farrell at 05/31/2023 03:16 PM

2 Wheel Alignment-NEW $109.99 +tax
Remove and Replace Front Strut Cartridge - Both $2080.47 +tax

Written by Ben Roberts at 05/31/2023 03:53 PM

Attached Images:



CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Invoice #0062010 5/18/2017 12:08 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 110727
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : C4S

Your Service Writer Today Is: MICK SOBTZAK Center: RETAIL

Service Requests:
LOF

Category Summary	Parts	Labor	Job Total
OIL CHANGE	$148.68	$29.99	$178.67

Technician	Service Description	Parts	Labor	Job Total
PJN	PORSCHE 993 OIL CHANGE SERVICE PERFORM OIL CHANGE SERVICE WITH UP TO 11 QUARTS OF 15W50 MOBIL 1 SYNTHETIC OIL AND 2 FILTERS, ONE ENGINE MOUNTED, ONE WHEEL WELL MOUNTED	148.68	29.99	178.67

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	99320720102	OIL FILTER	19.78	1	19.78
S		HAZMAT	1.34	1	1.34
S	99310720303	OIL FILTER	25.72	1	25.72
S		HAZMAT	1.74	1	1.74
S	15W50	MOBIL1 15W50	9.10	11	100.10

Payments:
MSTR CHARG VISA, $201.86, on 05/18/17
CardNo: [********1755], AuthorizationNo: [17900D]**

Repair Order Notes

*****TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.**

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

****TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.**

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$145.60
TOTAL LABOR	$29.99
SUBLET	$0.00
Supply Charg	$11.74
SUBTOTAL	$190.41
OTHER FEES	$3.08
SALES TAX	$11.45
INVOICE TOTAL	**$201.86**
PAID	$201.86
DUE	$0.00

COURTNEY TRUCK SERVICE

14205 W 62ND ST
EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Repair Order # 0054637
Date : 4/28/2014

Center : 8

Custon
Addre
C
CE t : CELL
WK : (952) - Ext :



Vehicle : 1996 PORS 911 SERIES
License : 664LVE **PRDT :** 01/96
VIN : WP0AA2992TS321853
Engine : 6-3600 3.6L SOHC **Trans :** STD
Mileage : 95020 **COLR :** BURGAND

Parts

Quan	Part Number	Description	Price
9.50	M1 15W50	15W50 MOBIL 1	76.00
1.00	99320720102	OIL FILTER	19.78
1.00		HAZMAT	1.26
1.00	99310720303	OIL FILTER	23.44
1.00		HAZMAT	1.49

		Payments:	
	AMERIC, on 04/28/14	**********1014	$170.88
	Auth#:580819		

Labor

Op	Tech	Description	Time	Charge
OIL503	AS	PORSCHE OIL CHANGE SERVICE		29.99

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Labor :	$29.99
Parts :	$119.22
Sublet :	$0.00
Other Fees :	$2.75
Supply Charg	$9.55
Subtotal :	$161.51
Sales Tax :	$9.37
Paid By : AMERICAN EXPRES	
Total :	$170.88
Pay Ref : **Paid :**	$170.88
Due :	$0.00

CTS

COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346

952-934-0931

GET OUR MOBILE APP ON APPLE OR ANDROID!

Invoice #0064367 5/11/2018 1:59 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 113805
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : C4S

Your Service Writer Today Is: MICK SOBTZAK Center: RETAIL

Service Requests:

1. REAR CV BOOT CRACKED- CHECK ESTIMATES 2. LOF
3. NEW SET OF REAR TIRES- MOUNT AND BALANCE
4. CEL WAS ON FOR P0410 HE CLEARED IT BUT CAN WE CHECK ROOT CAUSE.

Category Summary	Parts	Labor	Job Total
DRIVE TRAIN	$1,793.32	$629.20	$2,422.52
OIL CHANGE	$160.94	$29.99	$190.93
TIRES	$0.00	$56.00	$56.00

Technician	Service Description	Parts	Labor	Job Total
PJN	REMOVE AND REPLACE BOTH REAR CV AXLE SHAFTS.	1793.32	629.20	2422.52

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	996 332 024 13	AXLE ASSEMBLY-REAR	884 16	2	1768 32
S		FREIGHT	12 50	2	25 00

Technician	Service Description	Parts	Labor	Job Total
PJN	PORSCHE 993 OIL CHANGE SERVICE PERFORM OIL CHANGE SERVICE WITH UP TO 11 QUARTS OF 15W50 MOBIL 1 SYNTHETIC OIL AND 2 FILTERS, ONE ENGINE MOUNTED, ONE WHEEL WELL MOUNTED	160.94	29.99	190.93

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	99310720303	OIL FILTER	25.72	1	25 72
S		HAZMAT	1.74	1	1 74
S	99320720102	OIL FILTER	22.50	1	22 50
S		HAZMAT	1.53	1	1 53
S	15W50	MOBIL1 15W50	9.95	11	109 45

Technician	Service Description	Parts	Labor	Job Total
PJN	DISCARD 2 TIRES		6.00	6.00
PJN	LOW PROFILE MOUNT AND BALANCE 2 TIRES		50.00	50.00

Payments:
MSTR CHARG VISA, $2873.50, on 05/11/18
CardNo: [********1755], AuthorizationNo: [13548D]**

Repair Order Notes

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ Date: _____

TOTAL PARTS	$1,925.99
TOTAL LABOR	$715.19
SUBLET	$0.00
Supply Charg	$54.98
SUBTOTAL	$2,724.43
OTHER FEES	$28.27
SALES TAX	$149.07
INVOICE TOTAL	**$2,873.50**
PAID	$2,873.50
DUE	$0.00

CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Invoice #0059296 4/1/2016 2:19 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 106290
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : C4S

Your Service Writer Today Is: MICK SOBTZAK Center: RETAIL

Service Requests:
LOF, BLEW FAN BELT

Category Summary	Parts	Labor	Job Total
ACCESSORY DRIVE BELTS	$32.78	$159.36	$192.14
OIL CHANGE	$148.68	$29.99	$178.67

Technician	Service Description	Parts	Labor	Job Total
AS	PORSCHE 993 OIL CHANGE SERVICE PERFORM OIL CHANGE SERVICE WITH UP TO 11 QUARTS OF 15W50 MOBIL 1 SYNTHETIC OIL AND 2 FILTERS, ONE ENGINE MOUNTED, ONE WHEEL WELL MOUNTED	148.68	29.99	178.67

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	99310720303	OIL FILTER	25.72	1	25.72
S		HAZMAT	1.74	1	1.74
S	99320720102	OIL FILTER	19.78	1	19.78
S		HAZMAT	1.34	1	1.34
S	15W50	MOBIL1 15W50	9.10	11	100.10

Technician	Service Description	Parts	Labor	Job Total
AS	REMOVE AND REPLACE DRIVE BELTS.	32.78	159.36	192.14

	Part Number	Part Description	Part Price Each	Quantity	Extended
S	13X1085	BELT, V	12.45	1	12.45
S	10X775	BELT, V	10.35	1	10.35
S	10X760	BELT, V	9.98	1	9.98

Payments:
AMERICAN EXPRES, $409.01, on 04/01/16
CardNo: [********1014], AuthorizationNo: [593572]**

Repair Order Notes

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ Date: _____

TOTAL PARTS	$178.38
TOTAL LABOR	$189.35
SUBLET	$0.00
Supply Charg	$23.51
SUBTOTAL	$394.32
OTHER FEES	$3.08
SALES TAX	$14.69
INVOICE TOTAL	**$409.01**
PAID	$409.01
DUE	$0.00

CTS

COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346

952-934-0931

GET OUR MOBILE APP ON APPLE OR ANDROID!

Invoice #0067368 7/10/2019
Original Estimate #0003903 4:49 pm

Millrace
MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 115866
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : 993 C4S
Unit # 4 WHEEL DRIVE

Your Service Writer Today Is: JASON COOK Center: RETAIL

Service Requests:
REMOVE AND REPLACE BOTH LOWER TRACK RODS.

Category Summary	Parts	Labor	Job Total
ALIGNMENT	$0.00	$199.99	$199.99
SUSPENSION	$882.12	$327.80	$1,209.92

Technician	Service Description	Parts	Labor	Job Total
PJN	REMOVE AND REPLACE BOTH REAR, LOWER TRACK RODS.	882.12	327.80	1209.92
S	TRACK ROD 441.06 2 882.12			
PJN	PORSCHE 4 WHEEL ALIGNMENT		199.99	199.99

Payments:
MSTR CHARG VISA, $1526.80, on 07/10/19
CardNo: [********1755], AuthorizationNo: [74755C]**

Repair Order Notes

*****TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.**

PLEASE BE ADVISED: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

****TERMS:COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.**

We will charge $35.00 a day for all vehicles left in our lot after 48 hours.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$882.12
TOTAL LABOR	$527.79
SUBLET	$0.00
Supply Charg	$46.98
SUBTOTAL	$1,456.89
OTHER FEES	$0.00
SALES TAX	$69.91
INVOICE TOTAL	**$1,526.80**
PAID	$1,526.80
DUE	$0.00

CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346

952-934-0931

GET OUR MOBILE APP ON APPLE OR ANDROID!

Invoice #0067192 6/11/2019 3:18 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 115000
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : 993 C4S
Unit # 4 WHEEL DRIVE

Your Service Writer Today Is: KATE COURTNEY Center: RETAIL

Service Requests:
LOF MOBIL 1

Category Summary	Parts	Labor	Job Total
OIL CHANGE	$184.23	$29.99	$214.22

Technician	Service Description				Parts	Labor	Job Total
PJN	OIL CHANGE SERVICE INCLUDES REPLACE OIL AND OIL FILTER, LUBE CHASSIS WHERE APPLICABLE, PERFORM SAFETY INSPECTION.				184.23	29.99	214.22
S	MOBIL1 15W50	11.30	11	124 30			
S	OIL FILTER	22 13	1	22 13			
S	OIL FILTER ORIGINAL	37 80	1	37 80			

Payments:
MSTR CHARG VISA, $244.93, on 06/11/19
CardNo: [********1755], AuthorizationNo: [66826D]**

Repair Order Notes

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

PLEASE BE ADVISED: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS:COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

We will charge $35.00 a day for all vehicles left in our lot after 48 hours.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Customer Signature: _____ Date: _____

TOTAL PARTS	$184.23
TOTAL LABOR	$29.99
SUBLET	$0.00
Supply Charg	$15.67
SUBTOTAL	$229.89
OTHER FEES	$0.00
SALES TAX	$15.04
INVOICE TOTAL	**$244.93**
PAID	$244.93
DUE	$0.00

CTS

COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346

952-934-0931

GET OUR MOBILE APP ON APPLE OR ANDROID!

Estimate #0003903 6/11/2019 2:14 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 115000
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : 993 C4S
Unit # 4 WHEEL DRIVE

Your Service Writer Today Is: JASON COOK Center: RETAIL

Service Requests:

Category Summary	Parts	Labor	Job Total
ALIGNMENT	$0.00	$199.99	$199.99
SUSPENSION	$926.22	$327.80	$1,254.02

Technician	Service Description				Parts	Labor	Job Total
PJN	REMOVE AND REPLACE BOTH REAR, LOWER TRACK RODS.				926.22	327.80	1254.02
S	TRACK ROD	463 11	2	926.22			
PJN	PORSCHE 4 WHEEL ALIGNMENT					199.99	199.99

Estimate Notes

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$926.22
TOTAL LABOR	$527.79
SUBLET	$0.00
Supply Charg	$46.98
SUBTOTAL	$1,500.99
OTHER FEES	$0.00
SALES TAX	$73.23
ESTIMATE TOTAL	**$1,574.22**

RADON EDEN PRAIRE
MINNISOTA

BOSCH SERVICE

Ful' Service
mai
insp

Name_
Addres
Vehicle
Date _

Millrace
MOTOR CLUB

INSIDE VEHICLE		OUTSIDE VEHICLE	
OK	Needs Service	OK	Needs Service
☑	☐ Steering play	☑	☐ Headlights
☑	☐ Brake pedal	☑	☐ Taillights
☑	☐ Emergency brake	☑	☐ Brake lights
☐	☑ Horn	☑	☐ Turn signals
☑	☐ Windshield wipers	☑	☐ Backup lights
☐	☑ Windshield washers	☑	☐ License plate light
☑	☐ Mirrors	☑	☐ Wiper blades
☑	☐ Defroster	☑	☐ Tire inflation
		☑	☐ Tire condition

UNDERHOOD		UNDERNEATH	
Fluid levels:		Fluid leaks:	
☑	☐ Engine oil	☐	☑ Engine oil
☐	☐ Coolant	☐	☐ Cooling system
☑	☐ Brakes	☑	☐ Brakes
☐	☐ Auto transmission	☑	☐ Transmission
☐	☑ Battery	☑	☐ Differential
☑	☐ Power steering	☑	☐ Power steering
☐	☑ Windshield washer	☑	☐ Fuel tank & lines
☑	☐ Air filter	☑	☐ Shock absorbers/struts
☑	☐ V-belts	☑	☐ Tie rod ends
☐	☐ Radiator hoses	☑	☐ Ball joints
☐	☐ Heater hoses	☑	☐ Steering linkage
☐	☐ PCV valve & hose	☑	☐ Brake hoses
☑	☐ Vacuum hoses	☑	☐ Exhaust system/muffler
☑	☐ Distributor cap	☑	☐ Emergency brake cables
☑	☐ Spark plug wires	☐	☐ U-joints
☑	☐ Battery terminals	☑	☐ Differential lube
☐	☐ Read Computer	☑	☐ Brake pads & shoes

World Class Service For World Class Automobiles

AUTOHAUS DIEROLF

— SALES & SERVICE —

Audi ▪ B.M.W. ▪ Mercedes-Benz ▪ V.W.



429 W. CARMEL DR.
CARMEL, IN 46032
(317) 571-0800
M - Fri. 7:30 - 5:30

TYPE III MAINTENANCE & INSPECTION

BATTERY:

DATE_____

VOLTS 12.8

ALT. OUTPUT 14.1 25 Amp

VAC. P.S.I._____

ANTIFREEZE

PROTECTED TO

_____ -°F

==========

SUGGESTED REPAIRS NEEDED

Front Bumper Cover Scraped
Oil Leak = Case Halves
Rear Rotors = Slight Grooves = Pads OK
Exhaust Tips Scraped
Right WASHER NOZZLE = NOT Spraying
Horns Not Working
Parking Brake Indicator = Inop
Paint Orange Peel Left Fender
Dome Light Stays ON

MECHANIC /

DATE 11/19/13

Y TR
W 6
PR

CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
SERVICE@COURTNEYTRUCKSERVICE.COM

Invoice #0072903 5/24/2022 2:39 pm

Millrace
MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 119081
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : 993 C4S
Unit # 4 WHEEL DRIVE

Your Service Writer Today Is: JON FARRAND Center: RETAIL

Service Requests:
LOF
BRAKE FLUSH

Category Summary	Parts	Labor	Job Total
BRAKE	$0.00	$80.25	$80.25
OIL CHANGE	$152.22	$21.99	$174.21

Technician	Service Description				Parts	Labor	Job Total
PJN	OIL CHANGE SERVICE INCLUDES REPLACE OIL AND OIL FILTER, LUBE CHASSIS WHERE APPLICABLE, PERFORM SAFETY INSPECTION.				152.22	21.99	174.21
	MOBIL1 15W50	*11.49*	*11*	*126.39*			
	OIL FILTER	*24.19*	*1*	*24.19*			
	HAZMAT	*1.64*	*1*	*1.64*			
PJN	BLEED & FLUSH BRAKING SYSTEM					80.25	80.25

Payments:
MSTR CHARG VISA, $294.51, on 05/24/22
CardNo: [********1001], AuthorizationNo: [865654]**

Repair Order Notes

*****TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.**
*****OUR WARRANTY:12 Months or 12000 Miles on parts and labor, which ever comes first**

PLEASE BE ADVISED: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.
****TERMS:COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.**

We will charge $35.00 a day for all vehicles left in our lot after 48 hours.
Please be advised that there is a 3.5% fee for all credit card orders.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$150.58
TOTAL LABOR	$102.24
SUBLET	$0.00
Supply Charg	$17.45
SUBTOTAL	$271.91
OTHER FEES	$1.64
SALES TAX	$12.64
CREDIT CARD FEE	$9.96
INVOICE TOTAL	**$294.51**
PAID	$294.51
DUE	$0.00

CTS
COURTNEY TRUCK SERVICE

14205 W 62ND ST EDEN PRAIRIE, MN 55346
952-934-0931
SERVICE@COURTNEYTRUCKSERVICE.COM

Invoice #0071424 7/15/2021 2:17 pm

Millrace MOTOR CLUB

1996 PORSCHE 911 SERIES
6-3600 3.6L SOHC
VIN : WP0AA2992TS321853
Mileage : 118060
Trans : STD
License : 664LVE
PRDT : 01/96 COLR : BURGANI
Othe : 993 C4S
Unit # 4 WHEEL DRIVE

Your Service Writer Today Is: JON FARRAND Center: RETAIL

Service Requests:
lof
belt fraying- belts changed

Category Summary	Parts	Labor	Job Total
ENGINE MGMT	$70.92	$39.00	$109.92
OIL CHANGE	$173.30	$29.99	$203.29

Technician	Service Description			Parts	Labor	Job Total
PJN	**PORSCHE OIL CHANGE SERVICE: INCLUDES REPLACE OIL AND OIL FILTER, LUBE CHASSIS WHERE APPLICABLE, PERFORM SAFETY INSPECTION.**			**173.30**	**29.99**	203.29
	MOBIL 1 15W50	*10.28*	*11*	*113.08*		
	OIL FILTER	*24.19*	*1*	*24.19*		
	HAZMAT	*1.64*	*1*	*1.64*		
	OIL FILTER	*32.21*	*1*	*32.21*		
	HAZMAT	*2.19*	*1*	*2.19*		
PJN	**REMOVE AND REPLACE DRIVE BELTS**			**70.92**	**39.00**	109.92
	DRIVE BELT CONTITECH	*26.04*	*1*	*26.04*		
	DRIVE BELT CONTITECH	*20.25*	*1*	*20.25*		
	DRIVE BELT	*20.76*	*1*	*20.76*		
	FASTNER	*1.29*	*3*	*3.87*		

Payments:
MSTR CHARG VISA, $355.20, on 07/15/21
CardNo: [**********3089], AuthorizationNo: [0911I]

Repair Order Notes

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

***OUR WARRANTY:12 Months or 12000 Miles on parts and labor, which ever comes first

PLEASE BE ADVISED: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS:COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

We will charge $35.00 a day for all vehicles left in our lot after 48 hours.

Customer Signature: _____ Date: _____

TOTAL PARTS	$240.40
TOTAL LABOR	$68.99
SUBLET	$0.00
Supply Charg	$22.23
SUBTOTAL	$335.44
OTHER FEES	$3.82
SALES TAX	$19.76
INVOICE TOTAL	**$355.20**
PAID	$355.20
DUE	$0.00

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

Invoice #4505

03/14/2024 4:03 PM

Millrace MOTOR CLUB

1996 Porsche 911
WP0AA2992TS321853
Engine: 3.6L H6 (A) GAS FI
Plate: 664LVE
Fleet #: 4 WHEEL DRIVE
Odometer In: 121653
Odometer Out:

Advisor: Ben Roberts
Technician: Angel Cruz

GRAND TOTAL: $502.07
✔ PAID

SERVICES

1 INSPECT DRIVE BELTS

SUBTOTAL: $0.00

SQUEAL NOISE FROM UNDER THE HOOD

2 VEHICLE HEALTH INSPECTION

SUBTOTAL: $0.00

3 PORSCHE SYNTHETIC OIL CHANGE

SUBTOTAL: $172.34

LABOR

Drain and fill engine oil
Replace engine oil filter
Replace drain plug gasket
Lubricate suspension components as needed
Set tire pressures to specification
Perform multipoint inspection

PARTS	QTY
oc229 Oil Filter	1.0
Oil Filter	1.0
Leichtlauf HT 5W40	10.0

4 Remove and Replace Drive Belt - All 3

SUBTOTAL: $298.35

LABOR

PARTS	QTY
Drive Belt ContiTech V-Belt	1.0
Accessory Drive Belt	1.0
Accessory Drive Belt	1.0

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

Terms of Service:

1. "YES, DO THIS WORK"
I hereby authorize the corresponding service to be done along with the necessary materials.
2. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"
Werks Automotive staff may operate my vehicle for the purpose of testing, inspection, and delivery.
3. "NO PAYMENT, NO KEYS"
An express lien is acknowledged on my vehicle to secure the amount of services thereto.
4. "ONLINE COMMUNICATION OK"
I welcome email from Werks Automotive as a means of receiving copies of my estimate, work order, and invoice.
5. "HERE'S MY SIGNATURE"
I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these five terms.
6. 1 Year or 12,000 mile warranty on all work unless otherwise documented

GRAND TOTAL: $502.07

Total Labor: $282.39
Total Parts: $188.30
Total Fees: $0.00
Total Sublets: $0.00
Shop Supplies: $14.12
Sales Tax: $17.26

✔ **PAID**

03/14/2024 04:19 PM
Paid by Credit Card via Terminal: **$502.07**
VALUED CUSTOMER 37xx-xxxx-xxxx-xx01
Transaction ID: "ThwqliB32hRCRHbeRfi"

Signed:



Authorization:

Werks Automotive
14205 W 62nd St,
Eden Prairie, MN 55346
(952) 934-0931
service@WERKSautomotive.com

FINDINGS

PORSCHE SYNTHETIC OIL CHANGE	**$172.34 +tax**	Approved in person. 11:03am 3/14/24

Written by Ben Roberts at 03/14/2024 10:44 AM

Remove and Replace Drive Belt - All 3	**$360.92 +tax**	Approved in person. 11:03am 3/14/24

Written by Ben Roberts at 03/14/2024 10:44 AM

COURTNEY TRUCK SERVICE

14205 W 62ND ST
EDEN PRAIRIE, MN 55346
952-934-0931
VISIT US @: WWW.COURTNEYTRUCKSERVICE.COM

Repair Order #0057221
Date : 5/14/2015
Page : 1
Center : 1

Custor
Addr
C
CE kt : CELL
WK : (952) - Ext :

Millrace MOTOR CLUB

Vehicle : 1996 PORS 911 SERIES
License : 664LVE **PRDT :** 01/96
VIN : WP0AA2992TS321853
Engine : 6-3600 3.6L SOHC **Trans :** STD
Mileage : 98031 **COLR :** BURGAND

Op	Tech / Quan	Description / Part Number	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
		Service Requests: CK/RECHARGE A/C M1 LOF					
OIL993	AS	PORSCHE 993 OIL CHANGE SERVICE PERFORM OIL CHANGE SERVICE WITH UP TO 11 QUARTS OF 15W50 MOBIL 1 SYNTHETIC OIL AND 2 FILTERS, ONE ENGINE MOUNTED, ONE WHEEL WELL MOUNTED			29.99	148.68	178.67
	1.00	99320720102	OIL FILTER			19.78	
	1.00		HAZMAT			1.34	
	1.00	99310720303	OIL FILTER			25.72	
	1.00		HAZMAT			1.74	
	11.00	15W50	MOBIL1 15W50			100.10	
AIR015	AS	EVACUATE AND RECHARGE A/C SYSTEM - R134A			113.43	23.94	137.37
	1.20	R134	R134A REFRIGERANT LB			23.94	

		Payments: AMERICAN EXPRES, $349.58, on 05/14/15 CardNo: [************1014], AuthorizationNo: [524126]					

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

***TIRE SERVICE REMINDER: Wheels MUST BE RE-TORQUED at 100 miles after any sort of tire service. Please stop by at your convenience for this N/C service.

Please be advised: CTS is not responsible for damage or articles left in vehicle in case of fire, theft or any other cause beyond our control.

**TERMS: COD BUSINESS CUSTOMERS: Payment upon vehicle pick-up is preferred.

When necessary, and as a courtesy to our business customers, we extend ****NET 10 TERMS to accommodate multiple vehicle/driver situations.

Labor :	$143.42
Parts :	$169.54
Sublet :	$0.00
Other Fees :	$3.08
Supply Charg	$19.77
Subtotal :	$335.81
Sales Tax :	$13.77
Paid By : AMERICAN EXPRES Total :	$349.58
Pay Ref : Paid :	$349.58
Due :	$0.00