



PERFORMANCE CENTRE INC.

45839 YALE RD

CHILLIWACK, BRITISH COLUMBIA, V2P 2N6

Phone: 604 616 2400 TALK.TEXT. Email: service@carsfortoys.com. GST#: 796031375

Invoice #: 380

Date: 04/30/2026

Customer:

CARS FOR TOYS

45839 YALE ROAD

CHILLIWACK BRITISH COLUMBIA V2P 2N6

H: (604) 799-0700

Vehicle:

1991 ACURA NSX

Color: BLACK

VIN: JH4NA1158MT001872

License Plate:

Stock #: 309

Mileage: 0

Labor:

Services Performed	Labor(H)	Amount
REPLACE THE CLUTCH ASSEMBLY - DONE	10	1,800.00
MOUNT 4 RIMS AND TIRES- DONE	0.5	90.00
REFINISH RIMS - ALLOY WHEEL REPAIR #246367- DONE	0	0.00
DIAG: ALARM SYSTEM NOT WORKING	1	180.00
DIAG: MISSING FLAP ON CASSETTE PLAYER	0.25	45.00
Labor Subtotal:	11.75	2,115.00

Parts

Part Description	Code	Qty	Unit Price	Amount
ENGINE				
VALVE COVER GASKET	12341-PR7-A01	1	40.54	0.00
Parts Subtotal:				0.00

Subtotal: 2,115.00
PST: 0.00
GST: 0.00
Total: 2,115.00

Customer Signature

Date:

THANKS FOR YOUR BUSINESS



PERFORMANCE CENTRE INC.

45839 YALE RD

CHILLIWACK, BRITISH COLUMBIA, V2P 2N6

Phone: 604 616 2400 TALK.TEXT. Email: service@carsfortoys.com. GST#: 796031375

Invoice # 10053

Date: 07/01/2026

INVOICE

Customer:

CARS FOR TOYS
45839 YALE ROAD
CHILLIWACK BRITISH COLUMBIA V2P 2N6
H: (604) 799-0700

Vehicle:

1991 ACURA NSX
Color: BLACK
VIN: JH4NA1158MT001872
License Plate:
Stock #: 309
Mileage: 0

Labor:

Services Performed

	Labor(H)	Amount
5 Year Ceramic Coating and 2 Stage Paint Correction	20	2,400.00
Remove seats and shampoo interior	8	960.00
Labor Subtotal:	28	3,360.00

Parts

Part Description	Code	Qty	Unit Price	Amount
Parts Subtotal:				0.00

VOID VOID VOID VOID

Subtotal: 3,360.00
PST: 0.00
GST: 168.00
Total: 3,528.00

Customer Signature _____

Date: _____

THANKS FOR YOUR BUSINESS



PERFORMANCE CENTRE INC.

45839 YALE RD

CHILLIWACK, BRITISH COLUMBIA, V2P 2N6

Phone: 604 616 2400 TALK.TEXT. Email: service@carsfortoys.com. GST#: 796031375

Invoice #: 100475

Date: 06/05/2026

Customer:

CARS FOR TOYS

45839 YALE ROAD

CHILLIWACK BRITISH COLUMBIA V2P 2N6

H: (604) 799-0700

Vehicle:

1991 ACURA NSX

Color: BLACK

VIN: JH4NA1158MT001872

License Plate:

Stock #: 309

Mileage: 0

Labor:

Services Performed	Labor(H)	Amount
DIAG OIL LEAK	1	180.00
Oil leak present from both valve cover gaskets. Both gaskets have blown out of their respective slots. Found that the PCV valve is clogged. Requires replacement of the valve cover gaskets and PCV valve.		
REPLACE VALVE COVER GASKET	6	1,080.00
Replaced both valve cover gaskets, and PCV valve.		
DIAG BELT NOISE AT WARM IDLE	1	180.00
Tightened up both belts.		
DIAG INOPERABLE LOCK SYSTEM AND PASSENGER DOOR LOCK CYLINDER	1	180.00
Diagnose engine hesitation.	1	180.00
Replace the spark plugs	1	180.00
Replace the fuel filter	1	180.00
INSPECT FOR OIL LEAKS	0.3	54.00
FUEL TANK REMOVAL	0	0.00
REPLACE IGNITION COIL	0	0.00
Labor Subtotal:		12.3 2,214.00

Parts

Part Description	Code	Qty	Unit Price	Amount
ENGINE				
VALVE COVER GASKET SET	12030-PR7-010	1	106.86	106.86
EXHAUST SYSTEM				
PCV VALVE	KP106	1	15.12	15.12
FUEL SYSTEM				
DIRECT IGNITION COIL	30520-PY3-006	1	285.04	285.04
FUEL PUMP	16010-SL0-000	1	168.59	168.59
FUEL PUMP HANGER ASSEMBLY SEAL.	LO51	1	49.99	49.99
FUEL PUMP	SP1137	1	92.99	92.99
FUEL PUMP FILTER	STR13	1	20.69	20.69

See Next Page

IGNITION SYSTEM

LASER IRIDIUM SPARK PLUG	NGK6507	1	159.52	159.52
--------------------------	---------	---	--------	--------

Parts Subtotal: 898.80

Subtotal: 3,112.80
PST: 0.00
GST: 155.64
Total: 3,268.44

Customer Signature _____

Date: _____

THANKS FOR YOUR BUSINESS