
CARFAX Report

US $49.99

1987 Porsche 928 S4

89,577 mi | **VIN:** WP0JB092XHS860653

Coupe | 5.0L V8 F DOHC 32V | Gasoline | Rear wheel drive



NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX

9 Service History Records

31 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/15/26 at 8:59:00 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Summary
Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	No Recalls Reported
Basic Warranty No data reported to CARFAX.	No Data Reported

CARFAX Title History	Summary
Damage Brands Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon	No Problem

Odometer Brands Not Actual Mileage | Exceeds Mechanical Limits	No Problem

CARFAX Detailed History

Date	Mileage	Source	Comments
02/07/1987	35	Wisconsin Motor Vehicle Dept. Milwaukee, WI	**Odometer reading reported**
02/26/1992		Wisconsin Motor Vehicle Dept. Milwaukee, WI Title #920573P019	**Title or registration issued**
03/17/1995	64,150	Wisconsin Motor Vehicle Dept. Milwaukee, WI	**Odometer reading reported**
04/05/1995		Wisconsin Motor Vehicle Dept. Milwaukee, WI Title #9509557036	**Title or registration issued**
10/24/1996	67,000	Wisconsin Inspection Station	**Passed emissions inspection**
10/25/1999		Wisconsin Inspection Station	**Passed emissions inspection**
07/18/2000	68,695	Service Facility	**Vehicle serviced** - Fluids checked - Oil and filter changed
10/26/2000	69,000	Wisconsin Inspection Station	**Passed emissions inspection**
09/01/2001		Wisconsin Motor Vehicle Dept. Milwaukee, WI Title #9509557036	**Title or registration issued**
10/10/2002	71,000	Wisconsin Inspection Station	**Passed emissions inspection**
10/10/2002		Wisconsin Motor Vehicle Dept. Franksville, WI	**Registration updated when owner moved the vehicle to a new location**
05/09/2005		Wisconsin Motor Vehicle Dept. East Troy, WI Title #05129N10147	**Title issued or updated** - New owner reported - Exempt from odometer reporting - Vehicle color noted as Red
05/13/2005		INFINITI Milwaukee West Allis, WI 262-814-1100 infinitimilwaukee.com/ **4.6 / 5.0** 145 Verified Reviews **227** Customer Favorites	**Vehicle serviced**
12/20/2013		Michigan Motor Vehicle Dept. Dexter, MI Title #299B3540165	**Title issued or updated** - New owner reported
07/05/2019	84,800	Munk's Motors Waterford, MI 248-681-8081 **5.0 / 5.0** 40 Verified Reviews	**Vehicle serviced**

		79 Customer Favorites	
02/26/2020		Munk's Motors Waterford, MI 248-681-8081 **5.0 / 5.0** 40 Verified Reviews **79** Customer Favorites	**Vehicle serviced**
04/24/2020		Michigan Motor Vehicle Dept.	**Vehicle purchase reported**
06/05/2020		Michigan Motor Vehicle Dept. Farmington, MI Title #MI0005310513	**Title issued or updated** - New owner reported - Exempt from odometer reporting
09/18/2020		Michigan Motor Vehicle Dept. Farmington, MI	**Registration issued or renewed**
07/22/2023		Texas Motor Vehicle Dept. League City, TX Title #08431445119110225	**Title issued or updated** - New owner reported - Vehicle color noted as Red
07/25/2023	88,241	Specialty Car Solutions Houston, TX 713-645-2532	**Vehicle serviced** - Brakes checked - Safety inspection performed
10/05/2023	88,260	Specialty Car Solutions Houston, TX 713-429-0365 specialtycarsolutions.net/	**Vehicle serviced** - Brakes checked - Exhaust pipe seal replaced - Exhaust repaired - Front wheel bearing(s)/hub(s) replaced - Fuel tank straps replaced/repaired - Rear A/C actuator replaced - Tire(s) balanced - Wheel bearing(s) serviced - Wheel bearing(s)/hub(s) replaced
12/01/2023	88,418	Einar's Garage Houston, TX 713-767-7243 einarsgarage.com/ **5.0 / 5.0** 183 Verified Reviews **936** Customer Favorites	**Vehicle serviced**
01/30/2024	88,693	Specialty Car Solutions Houston, TX 713-429-0365 specialtycarsolutions.net/	**Vehicle serviced** - Brakes checked - Brake fluid flushed/changed
06/07/2024	89,385	Einar's Garage Houston, TX 713-767-7243 einarsgarage.com/ **5.0 / 5.0** 183 Verified Reviews **936** Customer Favorites	**Vehicle serviced** - Maintenance inspection completed - Brake fluid flushed/changed - Brake master cylinder replaced/repaired - Transmission cooler line(s) repaired/replaced - Transmission fluid changed - Valve body overhauled/resealed
06/19/2024		California Inspection Station Concord, CA	**Failed emissions inspection** - **Designated GROSS POLLUTER**
08/12/2024	89,559	California Inspection Station Concord, CA	**Failed emissions inspection**
08/13/2024	89,577	California Inspection Station Concord, CA	**Passed emissions inspection**
08/16/2024		California	**Title issued or updated**

	Motor Vehicle Dept. Pleasant Hill, CA	- New owner reported
04/29/2025	Montana Motor Vehicle Dept. Missoula, MT Title #AB0206111	**Vehicle purchase reported** - Title issued or updated - Title or registration issued - New owner reported - Vehicle color noted as Red
09/30/2026	Montana Motor Vehicle Dept. Missoula, MT Title #AB2910404	**Title issued or updated** - Correction to record - Vehicle color noted as Red

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

Glossary

Failed Emissions Inspection
The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

Gross Polluter
A Gross Polluter is a vehicle that fails an emissions inspection with below-standard scores. These vehicles can pollute as much as 18 times more than a vehicle that passes an emissions inspection. It is illegal to drive or sell a gross polluting vehicle in California, and it cannot be registered with the DMV. CARFAX recommends checking the latest Vehicle Inspection Report to confirm the proper repairs have been completed before purchasing.

New Owner Reported
When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History
CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued
A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX @CARFAXinc About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.

10/15/26 8:59:00 AM (CDT)

SHOW ME THE CARFAX

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1987 PORSCHE 928 vehicle (VIN: WP0JB092XHS860653), which is based on information supplied to CARFAX and available as of 10/15/26 at 9:59 AM (EDT).

Customer Signature **Date** **Dealer Signature** **Date**